

# ■ CONVERSION TABLE

*gauge* ↔ *mil* ↔ *micron* ↔ *mm*

Gauge	Mil	Micron	MM	INCH
50	0.50	12.5	0.0125	0.0005
60	0.60	15.0	0.015	0.0006
75	0.75	19.0	0.019	0.0007
100	1.00	25.0	0.025	0.0010
120	1.20	30.0	0.03	0.0012
160	1.60	40.0	0.04	0.0016
180	1.80	45.0	0.045	0.0018
200	2.00	50.0	0.05	0.0020
300	3.00	75.0	0.075	0.0030
400	4.00	100.0	0.1	0.0039
430	4.30	107.5	0.1075	0.0042
450	4.50	112.5	0.1125	0.0044
500	5.00	125.0	0.125	0.0049
600	6.00	150.0	0.15	0.0059
700	7.00	175.0	0.175	0.0069
800	8.00	200.0	0.2	0.0079
900	9.00	225.0	0.225	0.0089
1000	10.00	250.0	0.25	0.0098